

SECRET

OUT 55002

9 FEB 1965

1965 FEB 8 21 15Z

25X1

S E C R E T 082109Z

1. CAMERA B 15 WAS USED IN MISSION 3988 FLOWN ON 6 FEBRUARY 1965. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

- A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: ROLLER CHATTER IS PRESENT ALONG BOTH SIDES OF

THE FILM IN THE FIRST 300 FRAMES. EDGE STATIC EXISTS ALONG THE
OUTBOARD EDGE FOR THE FIRST 200 FRAMES. A CONTINUOUS PLUS DENSITY
LINE OCCURS 3.2" FROM THE INBOARD EDGE THROUGHOUT THE MISSION.

INK TRANSFER FROM THE LEADER IS PRESENT ON FRAMES 0001 AND 0300.

A DIG WITH ASSOCIATED SCRATCHES EXISTS IN FRAME 0900. TRANSVERSE

FOG STREAKS APPEAR ON THE LAST TWO FRAMES. MANUFACTURING SPLICES

OCCUR IN FRAMES 228 AND 1224.

C. 9L SIDE: INBOARD EDGE STATIC IS PRESENT IN THE FIRST 125 FRAMES. A MANUFACTURING SPLICE IS LOCATED IN FRAME 1954. FRAME 1500 CONTAINS AN INK SMEAR FROM THE TITLING ON THE HEAD IDENT.

D. BOTH SIDES: THE FRAMES ARE TITLED FROM 0000 TO 2143
ON EACH SIDE.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS DURING THE MISSION.

3. POSITIVE:

- A. PI SUITABILITY IS GOOD WHERE NOT DEGRADED BY ATMOSPHERICS.
- B. THE PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS DEGRADED APPROXIMATELY 45 PERCENT OF THE MISSION.

S E C R E T

//END OF MESSAGE//

SECRET

COPIES RECEIVED		7
CyNo.	Office	Act. Rec'd
1	SECRET	
2	SECRET	
	SECRET	
	SECRET	
	SECRET	
OF	SECRET	
HE	SECRET	
3,4,5	SECRET	✓
NSITY	SECRET	
	SECRET	
	SECRET	
00.	SECRET	
ERSE	SECRET	
ICES	Destroyed	

25X1